EPA/UIC INSPECTION REPO!
Inspection Type Compunity Inspection Frequency Property Authorization Authorization
Inspection Type Compunity Inventory No. 2419
Inspection Frequency Property 5 Authorization ABR
Violation Code N.A. Authorized to Inject Ny
Company/Operator KWB OL
Business Address 3300 (ST NATIONAL TWR. 15 F 5TH TUSS OK 7403
Individual Contacted Ne TED POPE Title SIDERVISOR
Lease Name & Well No. No Sign #59
Legal Description (6) (9)
Well Information: SWD/ER, Active/TA/P&A
Authorized Injection: Pressure 409 Rate N.A.
Long String Casing Size 6.62 w 5.5 LINER Tubing Size 2" REG.
Report of Conditions as of this Date:
Lease: Active/Inactive Well hooked up for injection: Yes/No
Injecting at time of inspection: Yes/No
Required fittings on tubing and casing/tubing annulus: Yes/No/Not Applicable
Injection Pressure; How Determined
Annular Pressure ; How Determined No Fittings
Injection Rate; How Determined
Well plugged at Surface: Yes/No/Undetermined
Samples TakenPhotographs Taken
Description of wellhead hookup and injection facility:
WELL IS EQUIPPED FOR OPERATION, LINE CONNECTED TO REG.
TRG. VALUE ON INJECTION WINE OPEN. 3,00 TRG. CSG.
PRESSURE UNAVAILABLE, NO FITTINGS, SEALED WITH PLUGS. COULD
NOT DETERMINE ANY FILLS "MUEMENT.
MR POPE STATES WELL HAS PEEN SHUT IN SINCE U.I.C. PROGRAM
REGANI
Weather Conditions and Observations SUNNY, COOL & DEVING.
Inspection Date 4-22-87 Time Arrived 11:45 Departed 12:20
Field Inspector MARK HENDRICKS
EPA Reviewer De Date 04/27/87